



Nevada State Contractors Board
NEWS RELEASE

www.nscb.state.nv.us

FOR IMMEDIATE RELEASE

Contact: Sonya Ruffin, APR
(702) 486-1100 x1139
or (775) 688-1141 x1139

**CONTRACTORS BOARD TAKES DISCIPLINARY ACTION
AGAINST ELEVEN CONTRACTORS**

(Henderson, NV) - At its meeting on March 29, 2005, the Nevada State Contractors Board adjudicated cases against eleven (11) licensed contractors.

Chief Roofing Inc., license number 51260 (Roofing and Siding) based out of Las Vegas, Nevada was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to comply with a notice to correct; failure to cooperate in the investigation of a complaint; willful disregard of building laws; failure to establish financial responsibility; failure to include license and monetary limit on a contract or proposal; failure to provide required Residential Recovery Fund disclosures; and misrepresentation of a material fact. The Board revoked the license of Chief Roofing Inc. Chief Roofing was ordered to pay restitution to the homeowner and assessed the cost of investigation.

Sports International Inc., license number 53551 (Carpentry) based out of Las Vegas, Nevada was found in violation of Nevada Revised Statute 624 for failure to pay for materials or services; failure to establish financial responsibility; failure to comply with a written request from the Board; and failure to cooperate in the investigation of a complaint. The licensee was fined \$4,000, assessed the cost of investigation, and ordered to comply with a payment plan for supplier.

SLR Plumbing and Heating, license number 39555 (Plumbing and Heating) based out of Las Vegas, Nevada was found in violation of Nevada Revised Statute 624 failure to pay for materials or services; failure to establish financial responsibility; failure to comply with a written request from the Board; and failure to keep in force a bond or cash deposit. The licensee was fined \$3,000 assessed the cost of investigation ordered to pay restitution. Fines and costs must be paid within 60 days or license will be revoked. A permanent letter of reprimand was placed in the licensee's file.

Legacy Construction Enterprises, license number 50647 (General Engineering) based out of Las Vegas, Nevada was found in violation of Nevada Revised Statute 624 failure to pay for materials or services; failure to establish financial responsibility; and failure to comply with a written request from the Board. The Board suspended the license of Legacy Construction Enterprises until a financial statement is submitted. The licensee was fined \$1,000, ordered to pay restitution, assessed the cost of investigation and ordered to submit to a Business Review. A permanent letter of reprimand was placed in the licensee's file.

Sealcoat Inc., license number 47633 (Custom Stamped Concrete Sealing and Cleaning) and ***Nu Turf***, license number 57615 (Landscape) based out of Las Vegas, Nevada was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to comply with a notice to correct; failure to cooperate in the investigation of a complaint; and failure to include license number and monetary limit on a contract or proposal. A one-year letter of reprimand was placed in the licensee's files; the licensee was fined \$3,000 and assessed the cost of investigation.

Pacific Concepts, license number 35736 (Residential and Small Commercial) based out of Pahrump, Nevada was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to

comply with a notice to correct; failure to cooperate in the investigation of a complaint; failure to diligently prosecute a construction project; bidding or contracting beyond established license limit; failure to establish financial responsibility; failure to comply with a written request from the Board; failure to include license number and monetary limit on a contract or proposal; failure to provide disclosures required by a general building contractor; abandonment of a construction project; and failure to report to the Board a change in address or personnel. The licensee was fined \$11,000, assessed the cost of investigation, and ordered to pay full restitution to homeowner. A permanent letter of reprimand was placed in licensee's file.

Pride Fire Protection LLC, license number 54873 (Fire Protection) based out of Reno, Nevada was found in violation of Nevada Revised Statute 624 for failure to pay for materials or services; failure to cooperate in the investigation of a complaint; failure to establish financial responsibility; and failure to comply with a written request from the Board. The Board revoked the license of Pride Fire Protection LLC. Pride Fire Protection was ordered to pay full restitution to damaged parties and assessed the cost of investigation.

Pacific Swimming Pool Plaster, license number 46842 (Spraying Mix Containing Cement) based out of Las Vegas, Nevada was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to comply with a notice to correct; failure to establish financial responsibility; failure to comply with a written request from the Board; failure to provide required Residential Recovery Fund disclosures; failure to comply with laws regarding residential pool and spa contracts; failure to provide disclosures required on residential pool contracts; failure to provide a list of subcontractors with a residential contract; failure to include license number and monetary limit on a contract or proposal; and failure to cooperate in the investigation of a complaint. The Board revoked the license of Pacific Swimming Pool Plaster; they were ordered to make full restitution to damaged parties and assessed the cost of investigation.

Desert Structures Inc. dba Four Seasons Sunrooms, license number 49443 (Residential and Small Commercial) based out of Boulder City, Nevada was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to comply with a notice to correct; failure to diligently prosecute a construction project; failure to comply with the terms of a construction contract; willful disregard of building laws; abandonment of a construction project; failure to establish financial responsibility; failure to comply with a written request from the Board; failure to provide required Residential Recovery Fund disclosures; failure to cooperate in the investigation of a complaint; and a fraudulent or deceitful act committed in the capacity of a contractor. The Board revoked the license of Desert Structures Inc. dba Four Seasons Sunrooms; they were ordered to make full restitution to damaged parties and assessed the cost of investigation.

Asphalt Services of Nevada Inc., license number 53346 (General Engineering) based out of Las Vegas, Nevada was found in violation of Nevada Revised Statute 624 for failure to pay for materials or services; failure to diligently prosecute a construction project; bidding or contracting beyond the scope of the license; failure to establish financial responsibility; failure to comply with a written request from the Board; failure to cooperate in the investigation of a complaint; failure to keep in force a bond or cash deposit; and failure to include license number and monetary limit on a contract or proposal. The Board revoked the license of Asphalt Services of Nevada Inc.; they were ordered to make full restitution to damaged parties and assessed the cost of investigation.

The Nevada State Contractors Board is committed to protecting the public's health, safety, and welfare through licensing and regulation of the construction industry. Under Nevada Revised Statutes, a licensee is subject to disciplinary action by the Board for failure to comply with the requirements of the laws or regulations governing contractors. Violations may result in Board action against the contractor's license. The State Contractors Board has the power to regulate contractors and discipline licensees who violate NRS 624. Disciplinary action may consist of a fine of up to \$10,000 per offense, order corrective action, suspension, revocation or other action.