



Nevada State Contractors Board
NEWS RELEASE

www.nscb.state.nv.us

FOR IMMEDIATE RELEASE

Contact: Sonya Ruffin, APR
(702) 486-1100 x1139
or (775) 688-1141 x1139

**CONTRACTORS BOARD TAKES DISCIPLINARY ACTION
INVOLVING TWELVE CONTRACTORS**

(Las Vegas, NV) – At its meeting on May 24, 2005, the Nevada State Contractors Board adjudicated cases involving twelve (12) contractors.

Pool Inc. dba Worldmark Pools & Spas, license number 56570 (Commercial and Residential Pools) based out of Las Vegas Nevada was found in violation of Nevada Revised Statute 624 for failure to diligently prosecute a construction contract; failure to comply with regulations of the Board governing contracts for the construction of residential pools and spas; failure to include required Residential Recovery Fund disclosures with a residential contract; a fraudulent or deceitful act in the capacity of a contractor; misrepresentation of a material fact; and failure to verify employment of the qualifying employee. The licensee was fined \$2,600, assessed the cost of investigation, required to take a law exam within 60 days, required to submit a proper contract to the Board within 30 days and required to submit to a Business Review.

Rebel Roofing, license number 48523 (Roofing) based out of Las Vegas, Nevada was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to comply with a notice to correct; failure to cooperate in the investigation of a complaint; acting in the capacity of a contractor beyond the scope of the license; failure to establish financial responsibility; failure to comply with a written request from the Board; and failure to provide required Residential Recovery Fund disclosures on a residential contract. The licensee was fined \$1,200, assessed the cost of investigation, ordered to pay \$3,769 restitution to the homeowner, ordered to submit a current financial statement to the Board, and ordered to submit to a Business Review.

Jensen Concrete, license number 40513 (Concrete Contracting) based out of Las Vegas, Nevada was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility; failure to comply with a written request from the Board; failure to cooperate in the investigation of a complaint; and failure to keep in force a bond or cash deposit. The licensee was fined \$1,000, assessed the cost of investigation and ordered to pay \$8,340.60 restitution to the supplier.

T C M Construction Services Inc. dba Cornerstone Roofing Co., license number 55659 (Roofing) based out of Las Vegas, Nevada was found in violation of Nevada Revised Statute 624 for substandard workmanship; willful disregard of building laws; failure to provide required Residential Recovery Fund disclosures on a residential contract; and failure to include license number and monetary limit on a contract or proposal. The licensee was fined \$400, assessed the cost of investigation and ordered to pay \$5,363.50 restitution to the homeowner.

Jack Coskey dba West Coast Pool & Spa, license number 24532 (Repair of Pools & Spas), **Worldmark Inc.**, license numbers 44153 (Commercial & Residential Pools) and 46201 (Residential and Small Commercial), and **Unique Environments**, license numbers 53715 (Commercial & Residential Pools), 53716 (Plumbing) and 53717 (Electrical Wiring) based out of Las Vegas, Nevada were found in violation of Nevada Revised Statute 624 for acting in the capacity of a contractor under a name other than that set forth upon the license; unlawful transfer of a license; misrepresentation of a material fact; association with an unlicensed person; combining with an unlicensed person to commit an unauthorized act; failure to report to the Board a change in address or personnel; failure to establish financial responsibility; and failure to comply with a written request from the Board. The licensee was fined \$10,000 and assessed the cost of investigation. The licenses were surrendered.

K M F Construction Inc., license numbers 50242 (Masonry) and 53006 (Concrete Contracting) based out of Las Vegas, Nevada was found in violation of Nevada Revised Statute 624 for acting in the capacity of a contractor under a name other than that set forth upon the license; acting in the capacity of a contractor beyond the scope of the license; and willful departure from plans or specifications. A permanent letter of reprimand was placed in the licensee's file; the licensee was fined \$1,000, and assessed the cost of investigation.

Gilbert Esqueda Garcia dba G.E.T. Roofing Company, license number 50277 (Roofing) based out of Henderson, Nevada was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to comply with a notice to correct; failure to cooperate in the investigation of a complaint; failure to obtain an appropriate lien release; willful disregard of building laws; failure to provide required Residential Recovery Fund disclosures with a residential contract; diversion of money or property; failure to appropriately prosecute a construction project causing material injury to another; failure to establish financial responsibility; and failure to comply with a written request from the Board. The Board revoked the license of Gilbert Esqueda Garcia dba G.E.T. Roofing Company. The licensee was ordered to make full restitution to all injured parties and pay the cost of investigation.

Sunstar Roofing Inc., license number 54134 (Roofing & Siding) based out of Las Vegas, Nevada was found in violation of Nevada Revised Statute 624 for failure to cooperate in the investigation of a complaint; failure to establish financial responsibility; failure to comply with a written request from the Board; and failure to keep in force a bond or cash deposit. The Board revoked the license of Sunstar Roofing Inc. The licensee was ordered to make full restitution to all injured parties and pay the cost of investigation.

Pro Tec Fireproofing Inc., license number 46787 (Coatings of Stucco and Cement) based out of Ridgefield, Washington was found in violation of Nevada Revised Statute 624 for disregard of industrial insurance laws; failure to establish financial responsibility; failure to respond to a written request from the Board; and failure to keep in force a bond or cash deposit. The Board revoked the license of Pro Tec Fireproofing Inc. The licensee was ordered to make full

restitution to all injured parties and pay the cost of investigation.

Aluminum Framar Glass Inc., license number 56907 (Glass & Glazing) based out of Henderson, Nevada was found in violation of Nevada Revised Statute 624 for misrepresentation of a material fact. The Board revoked the license of Aluminum Framar Glass Inc. The licensee was ordered to make full restitution to all injured parties and pay the cost of investigation.

The Business Review Program is one in which contractor's business practices and regulatory compliance is examined by NSCB investigative staff. The program is a part of NSCB's proactive investigative efforts.

The Nevada State Contractors Board is committed to protecting the public's health, safety, and welfare through licensing and regulation of the construction industry. Under Nevada Revised Statutes, a licensee is subject to disciplinary action by the Board for failure to comply with the requirements of the laws or regulations governing contractors. Violations may result in Board action against the contractor's license. The State Contractors Board has the power to regulate contractors and discipline licensees who violate NRS 624. Disciplinary action may consist of a fine of up to \$10,000 per offense, order corrective action, suspension, revocation or other action.
