

# e-News

Release

Nevada State Contractors Board

www.nscb.state.nv.us



Art Nadler, Public Information Officer  
(702) 486-1100 x1139  
or (775) 688-1141 x1139

## **NINE NEVADA CONTRACTORS DISCIPLINED** **BY CONTRACTORS BOARD**

(Reno, NV) – At its meeting on June 2, 2010, the Nevada State Contractors Board adjudicated cases involving nine contractors.

---

***Reynen & Bardis Communities Nevada, Inc.***, license number 61631 (Residential & Small Commercial), based out of Reno, NV, was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to include the Residential Recovery Fund information in a contract or proposal; and failure to establish financial responsibility. The licensee was fined \$200 and ordered to pay investigative costs. The license is suspended.

---

***Richard Walter Bryce, dba Northridge Remodeling***, license number 73081 (Carpentry, Remodeling & Repairs), based out of Reno, NV, was found in violation of Nevada Revised Statute 624 for diversion of funds; acting in the capacity of a contractor beyond the scope of the license; and failure to establish financial responsibility. The licensee was fined \$3,000; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

---

***Jose Luis Martinez, dba Powerhouse Lawn & Landscape***, license number 33895 (Landscaping) and ***Powerhouse Enterprises, Inc.***, license number 68865 (Residential & Small Commercial) based out of Reno, NV, were found in violation of Nevada Revised Statute 624 for submitting a bid when the license has been suspended or revoked; acting in the capacity of a contractor beyond the scope of the license; bidding or contracting in excess of the limit placed on the license; failure to include the monetary license limit and license number on a contract or proposal; for the partnership, corporation, firm or association participating in a prohibited act; and failure to establish financial responsibility. The licensee was fined \$400; ordered to pay investigative costs and provide a current financial statement that supports the license limit on the B-2 license.

-- more --

---

***Pinnacle Construction & Development, Inc.***, license number 56145 (Residential & Small Commercial), based out of Reno, NV, was found in violation of Nevada Revised Statute 624 for failure to respond to a written request from the Board; failure to comply with a written request from the Board; and failure to establish financial responsibility. The licensee was fined \$1,000; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

---

***Triple Crown Construction Development, Inc.***, license number 45825 (Residential & Small Commercial), based out of Reno, NV, was found in violation of Nevada Revised Statute 624 for failure to respond to a written request from the Board; failure to comply with a written request from the Board; failure to notify the Board of a bankruptcy; and failure to establish financial responsibility. The license was revoked.

---

***B S A Construction, LLC.***, license number 66728 (Residential & Small Commercial), based out of Dayton, NV, was found in violation of Nevada Revised Statute 624 for committing a fraudulent or deceitful act; failure to respond to a written request from the Board; failure to provide records requested by the Board; failure to maintain a bond or cash deposit; and failure to establish financial responsibility. The licensee was fined \$2,500 and ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

---

***Eagle Masonry***, license numbers 70010 and 70012 (Lathing & Plastering and Masonry), based out of Nampa, ID, was found in violation of Nevada Revised Statute 624 for failure to respond to a written request from the Board; failure to keep in force a bond or cash deposit; for the partnership, corporation, firm or association participating in a prohibited act; and failure to establish financial responsibility. The licensee was fined \$1,250; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The licenses were revoked.

---

***Zephyr Companies***, license number 53612 (General Engineering), based out of Incline Village, NV, had its license revoked.

---

***B & G Concrete***, license number 72853 (Concrete Contracting), based out of Reno, NV, had its license revoked.

---

**\*\*The Business Review Program is one in which a contractor's business practices and regulatory compliance is examined by NSCB investigative staff. The program is a part of NSCB's proactive investigative efforts.**

---

***The Nevada State Contractors Board is committed to protecting the public's health, safety, and welfare through licensing and regulation of the construction industry. Under Nevada Revised Statutes, a licensee is subject to disciplinary action by the Board for failure to comply with the requirements of the laws or regulations governing contractors. Violations may result in Board action against the contractor's license. The State Contractors Board has the power to regulate contractors and discipline licensees who violate NRS 624. Disciplinary action may consist of a fine of up to \$10,000 per offense, order corrective action, suspension, revocation or other action.***

---