



Art Nadler, Public Information Officer
(702) 486-1100 x1139
or (775) 688-1141 x1139

12 NEVADA CONTRACTORS DISCIPLINED **BY CONTRACTORS BOARD**

(Henderson, NV) – At its meeting on Feb. 24, 2010, the Nevada State Contractors Board adjudicated cases involving 12 contractors.

Damon Roy Innerarity, dba Innerarity Marble, license number 72571 (Marble) based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to take appropriate corrective action; failure to respond to a written request from the Board; acting in the capacity of a contractor beyond the scope of the license; failure to include the Residential Recovery Fund information on a contract or proposal; failure to include the monetary license limit and license number on a contract or proposal; willful disregard of the building laws of the state; and failure to establish financial responsibility. The licensee was fined \$5,250; ordered to pay investigative costs and pay \$7,941 in restitution. The license was suspended.

Aquaphina Pool & Spa of Nevada, license number 57119 (Commercial & Residential Pools) based out of Palmdale, CA, was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility and failure to keep in force a bond or cash deposit. The licensee was fined \$750; ordered to pay investigative costs and ordered to make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

Tomlyn Incorporated, dba Sign City USA, license number 43782 (Outdoor Advertising, Electrical Signs and Painted Signs) based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for willful disregard of the building laws of the state; failure to establish financial responsibility; and failure to keep in force a bond or cash deposit. The licensee was fined \$1,750; ordered to pay investigative costs and ordered to make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

Martin Metal Works, LLC., dba Martin Metal Designs, license number 62867 (Ornamental Metal), based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for failure to respond to a written request from the Board and failure to establish financial responsibility. The licensee was fined \$750; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

Blooming Vista Pools and Spas, LLC., license number 70670 (Commercial & Residential Pools), based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for failure to pay money due for materials or services; failure to respond to a written request from the Board; failure to keep in force a bond or cash deposit; and failure to establish financial responsibility. The licensee was fined \$2,000; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

Sweet Roots Landscaping, LLC., license numbers 58396, 57592 and 72992 (General Engineering, Landscaping and General Building) based out of Reno, NV, was found in violation of Nevada Revised Statute 624 for willful disregard of the laws of the state regarding industrial insurance; failure to establish financial responsibility; and for the partnership, corporation, firm or association participating in a prohibited act. The licensee was fined \$1,500; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The licenses were revoked.

Cabinetec, Inc., license number 27189 (Carpentry), based out of North Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for failure to include the monetary license limit and license number on a contract or proposal; failure to comply with the terms of a construction contract, thereby causing material injury to another; abandonment of a construction project; failure to respond to a written request from the Board; failure to take appropriate corrective action; failure to include the Residential Recovery Fund information on a contract or proposal; failure to notify the Board of a change in personnel or address within 30 days of the change; and failure to establish financial responsibility. The licensee was fined \$6,100; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

Regency Design & Landscaping, Inc., license numbers 50138, 48775, 48776, 66118 and 66016 (Residential & Small Commercial, Landscaping, Concrete Contracting, Masonry, Steel Reinforcing & Erection and Ornamental Metal), based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for failure to comply with a written citation and for the partnership, corporation, firm or association participating in a prohibited act. The licensee was fined \$500; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The licenses were revoked.

Horizon Concrete, Inc., license number 70194 (Concrete Contracting), based out of Henderson, NV, was found in violation of Nevada Revised Statute 624 for failure to respond to a written request from the Board and failure to establish financial responsibility. The licensee was fined \$1,000; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

R.G. & Associates Development, LLC., license number 53082 (Residential & Small Commercial), based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for failure to comply with the terms of a construction contract, thereby causing material injury to another; failure to take appropriate corrective action; failure to respond to a written request from the Board; and failure to establish financial responsibility. The licensee was fined \$2,000; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

Greencare Lawn & Landscape Enterprises, Inc., license number 60996 (Landscaping), based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility. The licensee was fined \$500; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

Las Vegas Concrete Pumping, Inc., dba Pools By Grube, license numbers 6887C, 6887E, 25953 and 25954 (Commercial & Residential Pools, Swimming Pool Tile & Coping, Concrete Contracting and Plastering) and ***Four Seasons Landscape and Sprinkler Design, Inc.***, license number 72065 (Landscaping) based out of Henderson, NV, was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to take appropriate corrective action; failure to establish financial responsibility; failure to respond to a written request from the Board; and for the partnership, corporation, firm or association participating in a prohibited act. The licensee was fined \$3,500; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The licenses were revoked.

****The Business Review Program is one in which a contractor's business practices and regulatory compliance is examined by NSCB investigative staff. The program is a part of NSCB's proactive investigative efforts.**

The Nevada State Contractors Board is committed to protecting the public's health, safety, and welfare through licensing and regulation of the construction industry. Under Nevada Revised Statutes, a licensee is subject to disciplinary action by the Board for failure to comply with the requirements of the laws or regulations governing contractors. Violations may result in Board action against the contractor's license. The State Contractors Board has the power to regulate contractors and discipline licensees who violate NRS 624. Disciplinary action may consist of a fine of up to \$10,000 per offense, order corrective action, suspension, revocation or other action.

###