



Nevada State Contractors Board  
***NEWS RELEASE***  
www.nscb.state.nv.us

---

**FOR IMMEDIATE RELEASE**

Art Nadler, Public Information Officer  
(702) 486-1100 x1139  
or (775) 688-1141 x1139

**CONTRACTORS BOARD TAKES DISCIPLINARY ACTION  
AGAINST FOUR CONTRACTORS**

*(Henderson, NV)* - At its meeting on Dec. 14, 2005, the Nevada State Contractors Board adjudicated cases involving four contractors.

---

***Innovative Concrete, LLC***, license number 58594 (Concrete Contracting) based out of Henderson, NV, was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to notify owner of required Residential Recovery Fund disclosures; and failure to establish financial responsibility. The licensee was fined \$1,000; assessed the cost of investigation; ordered to pay restitution of \$10,000 to homeowner within 10 days; and ordered to submit to a Business Review\*.

---

***D. K. Jensen Construction, Inc.***, license number 20829 (Residential and Small Commercial) based out of Boulder City, NV, was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to respond to a written request from the Board; failure to diligently prosecute a construction contract; failure to notify owner of Residential Recovery Fund disclosures; failure to establish financial responsibility; and failure to comply with a written request by the Board. The licensee was fined \$800; assessed the cost of investigation; ordered to repair substandard workmanship; and submit a financial statement.

---

***Construction Management Consultants, dba C M C Construction***, license number 44571 (General Building) based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility; failure to comply with a written request from the Board; failure to notify the Board of a change in address or personnel; failure to include license number and monetary limit on a contract or proposal; diversion of money or property; and failure to keep in force a bond or cash deposit. The licensee was fined \$800 and assessed the cost of investigation.

-- more --

---

***Advantage Awning Co.***, license number 50871 (Steel Reinforcing and Erection) based out of Henderson, NV, was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to respond to a written request from the Board; failure to establish financial responsibility; and failure to comply with a written request from the Board. The license of Advantage Awning Co. was revoked, the licensee was ordered to pay full restitution to all damaged parties; and assessed the cost of investigation.

---

**\*The Business Review Program is one in which a contractor's business practices and regulatory compliance is examined by NSCB investigative staff. The program is a part of NSCB's proactive investigative efforts.**

---

*The Nevada State Contractors Board is committed to protecting the public's health, safety, and welfare through licensing and regulation of the construction industry. Under Nevada Revised Statutes, a licensee is subject to disciplinary action by the Board for failure to comply with the requirements of the laws or regulations governing contractors. Violations may result in Board action against the contractor's license. The State Contractors Board has the power to regulate contractors and discipline licensees who violate NRS 624. Disciplinary action may consist of a fine of up to \$10,000 per offense, order corrective action, suspension, revocation or other action.*

---

###