



# NSCB News Release



**FOR IMMEDIATE RELEASE**  
September 7, 2018

**CONTACT:** Jennifer Lewis  
Public Information Officer  
(702) 486-1111

Scott Smith  
Public Information Specialist  
(702) 486-1165

## **BOARD REVOKES LICENSES IN AUGUST HEARINGS**

**RENO and HENDERSON, Nev.** – The Nevada State Contractors Board disciplined licensed contractors for violations of Nevada Revised Statutes Chapter 624 during its August 2018 hearings.

---

***M.C. Mohave Construction, LLC***, license numbers 25771A (residential and small commercial) and 75068 (plumbing and heating), based out of Las Vegas, Nev., was found in violation of failure to comply with the terms of a construction contract thereby causing material injury to another, failure to take appropriate corrective action, abandonment without legal excuse of any construction project, failure to prosecute a construction project or operation thereby causing material injury to another, failure to include the Residential Recovery Fund information on a contract or proposal, failure to respond and comply with a written request from the Board, substandard workmanship, failure to include the monetary limit or license number on a contract or proposal, failure of the general contractor to provide required disclosures to the owner of a single-family residence, willful disregard of the building laws of the state, acting in the capacity of a contractor beyond the scope of the license, wrongfully diverting money to a use other than that for which it was received, failure to pay any money due for any materials or services rendered, and failure to establish financial responsibility. The licenses were revoked. Investigative costs and restitution were not assessed, as the contractor has entered bankruptcy proceedings.

---

***Sharpline Multimedia, Inc.***, license number 71603 (low-voltage electrical), based out of Carson City, Nev., was found in violation for failure to comply with Nevada's building regulations, failure to comply with a written request from the Board and failure to establish financial responsibility. The license was suspended. Licensee was fined \$850 and assessed investigative costs.

---

***Into Homes Construction***, license number 58830 (carpentry maintenance and minor repairs) and ***Jefforey Stephen Bailey, dba All About Homes***, license number 78164 (residential and small commercial), based out of Reno, Nev., were found in violation for failure to pay for materials or services,

(more)

diversion of funds, bidding excess of the license limit, failure to keep in force a bond or cash deposit and failure to establish financial responsibility. The licenses were revoked. Licensee was fined \$4,000 and assessed investigative costs.

---

**Robertson Bright Industries, LLC**, license number 69146A (electrical), was found in violation of failure to establish financial responsibility. The license was placed on probation. Licensee was fined \$1,000.00 and assessed investigative costs. The license limit was reduced to \$1,000,000 and the licensee was provided 90 days to provide the Board a current financial statement that supports a \$5,000,000 license limit or a different license limit, at which time the probation status will be lifted. Failure to comply will result in suspension of the license.

---

**Dream Design, LLC**, license numbers 79799 (installing terrazzo and marble), 79786 (tiling), 79996 (finish carpentry), and 79800 (finishing floors), based out of Las Vegas, Nev., was found in violation for failure to respond to and comply with a written request from the Board, failure to include the Residential Recovery Fund information on a contract or proposal, and acting in the capacity of a contractor beyond the scope of the license. Licensee was fined \$2,200, assessed investigative costs and ordered to pay restitution of \$9,823 to the homeowner.

---

**Sustain Builders**, license number 78779 (residential and small commercial), based out of Las Vegas, Nev., was found in violation for failure to pay for materials or services, failure to establish financial responsibility, failure to keep in force a bond or cash deposit and failure to comply with a Board request for information or records. The license was revoked. Licensee was fined \$10,000 and assessed investigative cost.

---

**Sky Canyon Roofing, LLC**, license number 82399 (roofing and siding), based out of Las Vegas, Nev., was found in violation for willful disregard of the state's industrial insurance laws, failure to pay for materials or services, failure to establish financial responsibility, failure to respond to and comply with a written request from the Board, failing to provide true name, license number, or contact information of the person offering the service, failure to demonstrate experience, knowledge, and financial responsibility. The license was revoked. Licensee was fined \$7,000 and assessed investigative costs.

---

*The Nevada State Contractors Board is committed to protecting the public's health, safety, and welfare through licensing and regulation of the construction industry. Under Nevada Revised Statutes, a licensee is subject to disciplinary action by the Board for failure to comply with the requirements of the laws or regulations governing contractors. Violations may result in Board action against the contractor's license. The State Contractors Board has the power to regulate contractors and discipline licensees who violate NRS 624.*

*Disciplinary action may consist of a fine of up to \$10,000 per offense, order corrective action, suspension, revocation or other action.*

###

Visit our website: [www.nscb.nv.gov](http://www.nscb.nv.gov)

Join our social media network to receive current industry updates:

